

# Double Row Terminal Blocks

## 200 HB Series (High Barrier)

### 600 Volts

#### Specifications:

- Base, General Purpose Phenolic, 150° C
- Closed Back Design
- Screws, #6-32 Binder Head, Phil-Slot
- Terminals, Plated Brass
- 1-30 Poles
- 7/16" Centers
- Wire Range With Wire Binding Screw #12-#22 AWG – 20 Amps
- Wire Range With Sems Pressure Screw #12-#22 AWG Stranded Copper Wire Only, 20 Amps
- Will Accommodate Lugs For Wire Sizes #10-#16 AWG – 30 Amps
- The Suitability Of These Devices For Greater Currents Shall Be Determined In The End-Use Application
- UL Recognized File No. E62806
- CSA Certified File No. LR19766
- CE



Catalog #	# of poles	Dimensions	
		A	B
201HB	1	1.19	0.88
202HB	2	1.62	1.31
203HB	3	2.06	1.75
204HB	4	2.50	2.19
205HB	5	2.94	2.63
206HB	6	3.37	3.06
207HB	7	3.81	3.50
208HB	8	4.25	3.94
209HB	9	4.69	4.38
210HB	10	5.12	4.81
211HB	11	5.56	5.25
212HB	12	6.00	5.69
213HB	13	6.44	6.13
214HB	14	6.87	6.56
215HB	15	7.31	7.00

Catalog #	# of poles	Dimensions	
		A	B
216HB	16	7.75	7.44
217HB	17	8.19	7.88
218HB	18	8.62	8.31
219HB	19	9.06	8.75
220HB	20	9.50	9.19
221HB	21	9.94	9.63
222HB	22	10.37	10.06
223HB	23	10.81	10.50
224HB	24	11.25	10.94
225HB	25	11.69	11.38
226HB	26	12.12	11.81
227HB	27	12.56	12.25
228HB	28	13.00	12.69
229HB	29	13.44	13.13
230HB	30	13.87	13.56

MM = Dim x 25.4

Top Mounted Hardware is .250" Wide

#### Hardware Options: (Hardware options may affect ratings - consult factory)

- |           |  |             |
|-----------|--|-------------|
| (F1)      | = Full Quick Connect (0° flat)                               | See Page 93 |
| (F2)      | = Full Quick Connect (45° Bend)                              | See Page 93 |
| (F3)      | = Full Quick Connect (90° Bend)                              | See Page 93 |
| (S)       | = Full Solder  | See Page 94 |
| LL 200HB  | = Line to Line Jumper  | See Page 96 |
| 601 RJ(S) | = Multiple Position Jumper                                   | See Page 96 |
| (HS)      | = Half Solder  | See Page 94 |
| (HF1)     | = Half Quick Connect (0° Flat)                               | See Page 93 |
| (HF2)     | = Half Quick Connect (45° Bend)                              | See Page 93 |
| (HF3)     | = Half Quick Connect (90° Bend)                              | See Page 93 |
| (SP)      | = Sems Pressure Saddle Screw                                 | See Page 96 |
| (SPSE)    | = Sems Pressure Saddle Screw with External Tooth Lock Washer |             |
| LWW       | = Feed Thru Wire Wrap (.640)                                 |             |
| Y(L)      | = Feed Thru Solder (.625)                                    |             |
| YSY       | = Feed Thru Solder (.437)                                    |             |

